

DCR-HC40/HC40E

RMT-831

SONY®

LEVEL 2

SERVICE MANUAL

Ver. 1.7 2007.09

DCR-HC40

US Model
Canadian Model
Brazilian Model
Korea Model
Japanese Model

DCR-HC40E

AEP Model
UK Model
East European Model
North European Model
Australian Model
Chinese Model

DCR-HC40/HC40E

E Model
Hong Kong Model
Tourist Model

SUPPLEMENT-5

File this supplement-5 with the service manual.
(DI07-121)


Subject :

- Change of Repair parts list

5. REPAIR PARTS LIST

5-1. EXPLODED VIEWS

 : Added portion

Page	Before change	After change																					
5-8	5-1-6. CABINET (L) SECTION																						
	<table border="1"><thead><tr><th>Ref. No.</th><th>Part No.</th><th>Description</th></tr></thead><tbody><tr><td>272</td><td>A-7112-785-A</td><td>VC-352 BOARD, COMPLETE (SERVICE) (HC40)</td></tr><tr><td>272</td><td>A-7113-240-A</td><td>VC-352 BOARD, COMPLETE (SERVICE) (HC40E)</td></tr></tbody></table>	Ref. No.	Part No.	Description	272	A-7112-785-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40)	272	A-7113-240-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40E)	<table border="1"><thead><tr><th>Ref. No.</th><th>Part No.</th><th>Description</th></tr></thead><tbody><tr><td>272</td><td>A-7112-785-A</td><td>VC-352 BOARD, COMPLETE (SERVICE) (EXCEPT HC40 : Korea) (Note)</td></tr><tr><td>272</td><td>A-7112-785-B</td><td>VC-352 BOARD, COMPLETE (SERVICE) (HC40 : Korea) (Note)</td></tr><tr><td>272</td><td>A-7113-240-A</td><td>VC-352 BOARD, COMPLETE (SERVICE) (HC40E) (Note)</td></tr></tbody></table>	Ref. No.	Part No.	Description	272	A-7112-785-A	VC-352 BOARD, COMPLETE (SERVICE) (EXCEPT HC40 : Korea) (Note)	272	A-7112-785-B	VC-352 BOARD, COMPLETE (SERVICE) (HC40 : Korea) (Note)	272	A-7113-240-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40E) (Note)
	Ref. No.	Part No.	Description																				
272	A-7112-785-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40)																					
272	A-7113-240-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40E)																					
Ref. No.	Part No.	Description																					
272	A-7112-785-A	VC-352 BOARD, COMPLETE (SERVICE) (EXCEPT HC40 : Korea) (Note)																					
272	A-7112-785-B	VC-352 BOARD, COMPLETE (SERVICE) (HC40 : Korea) (Note)																					
272	A-7113-240-A	VC-352 BOARD, COMPLETE (SERVICE) (HC40E) (Note)																					
																							

Note :

As version numbers of the VC-352 board and microcontroller are upgraded, the microcontroller data need to be change.
To change the microcontroller data, see page 5 of Supplement-4.